


**PARTS DIAGRAM FOR PRISMO™**

**Catalog #TS7100**



<b>1 ZPTSPM-01</b>	Motor Side Plate	<b>14 ZPTSPM-75</b>	Retaining Ring
<b>2 ZPTSPM-02</b>	Flat Side Plate	<b>15 ZPTS2-21</b>	M3 x 12mm Short Standoff } Part of motor
<b>3 ZPTS2-05</b>	Black Motor Cover Cap	<b>16 ZPTS2-22</b>	M3 x 22mm Long Standoff } side plate
<b>4 ZPTS2-06</b>	Teflon Guide Wheel	<b>17 ZPTS2-25</b>	5.6 x .142 Black Tie Wrap
<b>5 ZPTS2-07</b>	Teflon Washer	<b>18 ZPTS2-297.1</b>	Motor - 297:1
<b>6 ZPTS2-08</b>	1/8" Motor Rubber Gromets	<b>19 ZPTS2-40</b>	6-Step Transformer (Includes #20 & #23)
<b>7 ZPTS2-09</b>	33mm Motor Pulley	<b>20 ZPTSSOLO-11</b>	Black Heat Resistant Sleeving
<b>8 ZPTS2-11</b>	M4 Flat Washer	<b>21 ZPTSPM-64</b>	4-15/16" ODX4 7/16" IDX 1/64" THK
<b>9 ZPTSPM-23</b>	M3 x 8mm C/S Screw BLK (6)	<b>22 ZPTSPM-32</b>	4-15/16" ODX4 7/16" IDX 1/32" THK
<b>10 ZPTSPM-24</b>	4-40 x 3/8" C/S Screw BLK (3)	<b>23 ZPTSSP-05</b>	Heat Shrink Tube 1/4" BLK
<b>11 ZPT2-14</b>	M4 x 6mm Set Screw	<b>24 TS7130</b>	3-Sided Prism
<b>12 ZPT2-16</b>	Short Drive Belt	<b>25 TS7150</b>	5-Sided Prism
<b>13 ZPTSPM-70</b>	Gobo Ring		